



# HLL Temporary Limitations Notice

TO:	ALL PILOTS	DATE:	31 May 2022
TLN NUMBER:	10 - 2022		
SUBJECT:	<b>Beryl A Helideck Netlight Removal</b>		

**1. Comments**

Apache have removed the helideck Frictape Net lights to carry out repainting around the perimeter. The project is expected to last until further notice, during which the "Circle H" lights will not be fitted, therefore pilots will need to take care to land in the middle of the helideck to ensure sufficient obstacle clearance.

For this reason, helicopter operations will be restricted to **DAY ONLY**.

Wind speed limitations are not affected as the deck has an adequate friction coefficient.

Beryl A will notify the current deck condition on every pre-flight weather brief and on initial approach.

**2. Photo/Dwg N/A**

**3. Existing HLL limitations**

***Beryl A***

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
NW	All	<b>Platform</b> <ul style="list-style-type: none"> <li>• Possible turbulence from derricks</li> <li>• Table 1 (T) if overflight of South foam monitor platform, adjacent satellite dish, south lifeboat station or east accommodation roof is unavoidable-</li> <li>• Remain 60m clear of Skene flare due to no warning of flare shutdown and cold flaring present.</li> <li>• Deck slope in excess of 1:100 (1:50)</li> <li>• Cleared for S92</li> <li>• Frictape net lights fitted</li> </ul>	5:1  Misc.	<b>Access points and platform structure N/W and N/E infringe sector.</b> <b>Incorrect 't' value marked</b> <b>Deck surface breaking up</b>

**4. Additional limitations**

***Beryl A***

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		DAYLIGHT OPS ONLY		Frictape Net lights removed

These restrictions/changes shall remain in force until (unless previously revoked or suspended)	<b>Until Further Notice</b>
---	-----------------------------

*Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect*