



HLL Temporary Limitations Notice

TO:	ALL PILOTS	DATE:	9 Sept. 2022
TLN NUMBER:	26 – 2022		
SUBJECT:	Global Producer 3 Helideck Lighting		

1. Comments

Some of the lights around the H have failed. The lights are individual and sporadically located around the H which remains discernible and therefore, not currently at the point where a day only restriction is necessary. Replacements have been ordered but the lead time is 18-20 weeks. The concern is that more lights could fail and so the situation is being closely monitored.

If the lighting deteriorates to the point where one or more sides of a leg of the H goes out and it becomes undiscernible, operations will be restricted to 'day only'.

2. Photo/Dwg - Not applicable

3. Existing HLL limitations

Global Producer III

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		FPSO with BOW helideck = Cat 1 <ul style="list-style-type: none"> Table 1(T) to be applied if overflight of foam monitor platforms is unavoidable Aiming Circle offset due to obstructions in the LOS Approved friction surface - no net HMS Rev.9B fitted. CAA Dispensation for Atex Lights 	LOS 5:1 Misc.	HVAC shaft approx. 1.7m adl @ approx. 3.3m from SLA Helifuel skid approx 1.7m adl @ approx. 3.3m from SLA Foam monitor platforms infringe sector. - Fwd, Port and Starboard approx. 3.7m from edge of SLA. Various deck structures port and starboard aft of helideck. HMS Repeater lights not fitted.

4. Additional limitations

Global Producer III

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		Lighting Reports required.		

These restrictions/changes shall remain in force until (unless previously revoked or suspended)

28 February 2023

Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect