



# HLL

## TEMPORARY LIMITATION NOTICE

---

**NOTICE TO:** All Pilots

---

**TLN NUMBER:** 007-2025

---

**SUBJECT:** Haewene Brim Crane Boom out of stowed position but stationary during helicopter operations

---

**TLN ISSUED:** 8 April 2025

---

**EXPIRY DATE:** 8 July 2025

---

# 01 | OVERVIEW

PRIMARY ASSET	SECONDARY ASSET(S)
Haewene Brim	N/A

## COMMENTS

Haewene Brim crane boom out of stowed position due to diving operations. Helicopter operations can commence as normal as long as crane boom is stationary during flight operations.

Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect.

# 02 | IMAGES / DRAWINGS

N/A

# 03 | HLL LIMITATIONS

## HAEWENE BRIM

LIMITATION/COMMENT	WIND (T°)	SPEED (Kts)	NON-COMPLIANCES
<b>EXISTING LIMITATIONS</b>			
<ul style="list-style-type: none"> <li>&gt; Table 1 (T) if overflight of the forward monitor platforms cannot be avoided on take-off.</li> <li>&gt; Remain clear of flare at all times due to automatic ignition of released gases.</li> <li>&gt; HMS Rev 9b + Repeater Lights fitted.</li> </ul>			<p><b>210°:</b></p> <ul style="list-style-type: none"> <li>&gt; Nil.</li> </ul> <p><b>150°:</b></p> <ul style="list-style-type: none"> <li>&gt; Guardrail on aft walkway up to 0.9m adl.</li> </ul> <p><b>5:1:</b></p> <ul style="list-style-type: none"> <li>&gt; Forward foam monitor platforms (port&amp;stbd) approx. 3m from edge of SLA.</li> <li>&gt; Bridge wings Port and Starboard</li> </ul> <p><b>Miscellaneous:</b></p> <ul style="list-style-type: none"> <li>&gt; Flare is live at all times but flames intermittently.</li> <li>&gt; Flare ignited or floodlit during hours of darkness.</li> </ul>
<b>ADDITIONAL LIMITATIONS</b>			
> Nil.			> Nil.