


HLL
Temporary Limitations Notice

TO:	ALL PILOTS	DATE:	20 November 2024
TLN NUMBER:	050 - 2024		
SUBJECT:	Culzean ULQ with Valaris Stavanger alongside		

1. Comments

The Culzean ULQ will have the Valaris Stavanger alongside for approximately 13 months.

2. Photo/Dwg



3. Existing HLL limitations

Culzean ULQ

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
All	<45kts ≥45kts	<ul style="list-style-type: none"> • Table 1(T) if overflight of 5:1 obstructions unavoidable • Landings should be within +/- 15 degrees of reported wind direction • Nil landings due to non-compliant friction surface • <i>Note: Reported wind direction should be treated with caution due to the effects of crane & platform structures from all directions. Wind speed specifically should be treated with caution between 075-165 degrees.</i> <p><i>Non Compl</i></p>		

Valaris Stavanger

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		<ul style="list-style-type: none"> • No flight operations whilst afloat (No P/R/H equipment) • No DG's to be uplifted 	Misc	Whip aerials stbd side, accommodation port side are close to 210 boundary

These restrictions/changes shall remain in force until (unless previously revoked or suspended)	31 December 2025
---	-------------------------

Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect