


TO:	ALL PILOTS	DATE:	18 December 2024
TLN NUMBER:	054 - 2024		
SUBJECT:	<b>SF OCP with Seafox 2 alongside</b>		

**1. Comments**

The SF OCP will have the Seafox 2 alongside for approximately 6 months. The SF OCP helideck will be closed during this time.

*Note: Turbulence reports requested due to position and shape of SF OCP.*

**2. Photo/Dwg**



### 3. Existing HLL limitations

#### Seafox 2

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		<b>Jack Up</b> <ul style="list-style-type: none"> <li>• Table 1(T) if overflight of 5:1 infringements unavoidable</li> <li>• No helicopter operations whilst under tow</li> <li>• Approved for S92 (12T)</li> <li>• No planned shutdowns - only four tie-down points</li> </ul>	<b>150°</b>  <b>5:1</b>  <b>Misc</b>	<b>Handrails port &amp; stbd aft - minor infringement</b>  <b>Forward access point 4.5m from SLA, vessel structure port and starboard aft</b>  <b>DGs not to be shipped by air from this location - no qualified shipper &amp; packer</b>

### 4. Additional limitations

#### SF OCP

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		<b>Helideck Closed for the duration of this TLN</b>		

#### Seafox 2

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
<b>160° - 250°</b>	<b>&lt;10kts</b>	<b>No restriction</b>		
	<b>10-20 kts</b>	<b>Apply Table 2</b>		
	<b>&gt;20kts</b>	<b>Nil Landings</b>		

These restrictions/changes shall remain in force until (unless previously revoked or suspended)	<b>31 May 2025</b>
---	--------------------

*Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect*