


TO:	ALL PILOTS	DATE:	9 January 2025
TLN NUMBER:	003 - 2025		
SUBJECT:	Hamilton Platform with Irish Sea Pioneer alongside		

**1. Comments**

The Hamilton Platform will have the Irish Sea Pioneer alongside for approximately 4 months. The Hamilton will be closed during this time.

**2. Photo/Dwg**



### 3. Existing HLL limitations

#### Hamilton

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		No automatic fire-fighting facilities	210°	Outside edge of perimeter net frame up to 300mm adl.
		Aiming circle offset	5:1	NE & SW access points and small crane arm on SW side.
		Table 1 (T) if overflight of 5:1 items unavoidable	Misc	Height limitation in 210 OFS & 1st sector of LOS is 150mm.
		Deck closed when Jack-up alongside		

#### Irish Sea Pioneer

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		Table 1(T) if overflight of 5:1 items is unavoidable	210°	Outer edge of perimeter net frame 290mm.
		No helicopter operations whilst on the move due to non-compliant HMS.	150°	Inboard foam monitor behind chevron at 250mm adl. Foam pipe marginal infringement for AW169 operations.
		Approved for AW169 operations	5:1	Forward access perimeter netting and lifeboat stations (port and starboard) infringe sector.

### 4. Additional limitations

#### Hamilton

Wind (T°)	Kts	Limitation /Comment		Non-Compliances
		Helideck Closed for the duration of this TLN.		

These restrictions/changes shall remain in force until (unless previously revoked or suspended)	<b>20 April 2025</b>
---	----------------------

Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect